

Figure 1




Figure 2

FIG. 3




Figure 3




Figure 4




Figure 5




Figure 6

FILESYSTEM\_THRESHOLD\_EXCEEDED




Figure 7A




Figure 7B






Figure 8





Figure 9






Figure 11




Figure 12

FIG. 13




Figure 13

Figure 14a

Figure 14b

Figure 14c

Figure 14d

2025 OCT 24 09:50




Figure 14a






Figure 14b




Figure 14c




Figure 14d

FIGURE 15

# GUI (server) & Manager communication




Figure 15

FOOT" 0234650





Figure 16

100

FOOT 0422550



FOOT 042650

108

Manage Disks - Tivoli Console (Driver 7)

Console Tools View Manage Disks Window Help

archi

troodon

trex

raptor

Host IP Address is 9.112.56.123

archi Properties

Accessible LUNs

Capacity in MBs	Vendor	Product	Revision	Unit Number	Status	Assigned To
4875	UNISYS	006073ST191	1901	LAC66200		
10500	UNISYS	006073ST191	1901	LAD88390		
22345	IBM	2105E20	1005	40BFCA20		
22345	IBM	2105E20	1005	40CFCA20		
22345	IBM	2105E20	1005	40BFCA34		
22345	IBM	2105E20	1005	40BFCA34		
22345	IBM	2105E20	1005	40BFCA25		
22345	IBM	2105E20	1005	40CFCA25		
8520	EMC	SYMMETRIX	5265	37012720Z		
4875	SEAGATE	ST1971FC	CC95	37028120Z		
4875	UNISYS	39 BYTES LO	901L	AC66203	Assigned	
10500	UNISYS	39 BYTES LO	1901	LAM14520	Assigned	
22345	IBM	2105E20	1005	40BFCA24	Assigned	
22345	IBM	2105E20	1005	40CFCA24	Unassign P	
8520	EMC	SYMMETRIX	5265	37012720C	Assigned	

Total: 19 displayed, 10 selected

Welcome to the Tivoli Console

View Storage Devices

Manage Disks

Assign LUN

Unassign LUN

Reassign LUN

112a

112b

112c

112d

110

114

Figure 18

10500T 0/EE2/660





Figure 19



FOOT 0/E2/550



FOOT" 04E2660

## Clearing the Filter

**Manage Disks - Tivoli Console (Driver 7)**

Console Help View Manage Disks Window Help

archi

Host IP Address is 9.112.56.123

**Host Properties**

**Accessible LUNs**

Capacity in MBs	Vendor	Product	Revision	Unit Number	Status	Assigned To Other	Logical Unit
<no filter>	<no filter>	<no filter>	<no filter>	<no filter>	<no filter>	<no filter>	<no filter>
22,345	IBM	2105E20	1005	40CFCA24	Unassign Pending		LU group1
10,600	UNISYS	006073ST191	1901	LAD88397	Assigned		LU group1
22,345	IBM	2105E20	1005	40BFCA24	Assigned		LU group1
8,520	EMC	SYMMETRIX 5285	37012720C	37012720C	Assigned		LU group1
10,500	UNISYS	006073ST191	1901	LAD88390			LU group1
22,345	IBM	2105E20	1005	40BFCA20			LU group1
22,345	IBM	2105E20	1005	40CFCA20			LU group1
22,345	IBM	2105E20	1005	40BFCA34			LU group1
22,345	IBM	2105E20	1005	40DFCA34			LU group1
22,345	IBM	2105E20	1005	40BFCA25			LU group1
22,345	IBM	2105E20	1005	40CFCA25			LU group1
8,520	EMC	SYMMETRIX 5285	37012720Z	37012720Z			LU group1

Total 19 LUNs Displayed 12 Selected 10

Assign LUN Unassign LUN Reassign LUN

Welcome

Manage LUNs

Figure 21

Custom Filtering

Manage Disks - Tivoli Console (Driver 7)

Console Edit View Manage Disks Window Help

archi troodon trex raptor vega

Host IP Address is 9.112.56.123

Host Properties

Accessible LUNs

Capacity in MBs 5000

Filter: At least At most OK

22,345	EMC	SYMMETRIX	5265	40CFCA24	Unassign Pending	<no filter>	LU group1
8,520	EMC	SYMMETRIX	5265	LAC68203	Assigned	<no filter>	LU group1
4,875	EMC	SYMMETRIX	5265	LAD98397	Assigned	<no filter>	LU group1
4,875	EMC	SYMMETRIX	5265	40BFCA24	Assigned	<no filter>	LU group1
0	SEAGATE	ST1971FC	CC95	37012720C	Assigned	<no filter>	LU group1
4,875	UNISYS	06073ST191	1901	37028120C	Assigned	<no filter>	LU group1
10,500	UNISYS	06073ST191	1901	37028120C	Assigned	<no filter>	LU group1
22,345	IBM	2105E20	1005	LAC68300	Assigned	<no filter>	LU group1
22,345	IBM	2105E20	1005	40BFCA20	Assigned	<no filter>	LU group1
22,345	IBM	2105E20	1005	40CFCA20	Assigned	<no filter>	LU group1
22,345	IBM	2105E20	1005	40BFCA34	Assigned	<no filter>	LU group1
8,520	EMC	SYMMETRIX	5265	40BFCA34	Assigned	<no filter>	LU group1

Total 19 Displayed 19 Selected 0

Welcome

Manage LUNs

Assign LUN Unassign LUN Reassign LUN

Figure 22




Figure 23




Figure 24

FOOT" 02E2660




FIGURE 25

Footnote 2/650




FIGURE 26




Figure 27



FOOT OF 260




Figure 28

TD500T 02E2660




Figure 29

103001" 042/650




Figure 30

FOOT 0/2/650




Figure 31

10500T 0/622660





Figure 32

Figure 33






IBM DOCKET NO. SJ09-2001-0098

FOOT OF 66

Figure 35









FIGURE 36

Figure 37






Figure 38

TOP SECRET




Figure 39

TOP SECRET




Figure 40

46/48

IBM DOCKET NO. SJ09-2001-0098




Figure 41

[illegible]

IBM DOCKET NO. SJ09-2001-0098




Figure 42

FOOT REF 60




Figure 43